Print Page Click Here

OASIS RESULT: 1FMSU45P85EC14606 | USA EN | **04/21/2010 09:33:03 FCXWS446**

© Copyright 2002-2010 Ford Motor Company. All rights reserved.

VEHICLE INFORMATION

VEHICLE DESCRIPTION 2005 EXCURSION	**BODY STYLE** 4 DR EDDIE BAUER 4X4	**ENGINE** 6.0L DIESEL DI V8
TRANSMISSION TORQSHIFT	**AXLE CODE** C1	**ENGINE CALIBRATION** 5L110M0A
PAINT COLOR EBONY SOLID C/C	**RADIO** AM/FM STRO/CD CHANGER/CLK	**GROSS VEHICLE WEIGHT** 9200 LB. GVW
AXLE RATIO 3.73 FINAL DRIVE RATIO	**WHEEL SIZE** 7.0 X 16" 6 WINDOW ALUM WHEEL	**FRONT TIRE** LT265/75R-16E OWL A-T

WARNING MESSAGES

VERIFY STATE REGISTRATION, VIN MAY BE ELIGIBLE FOR CALIFORNIA EMISSIONS WTY

ARN MESSAGES

ATTENTION TECHNICIANS AND SERVICE MANAGERS:
INSTALL 6A642-CA KIT WHEN REPLACING EGR COOLER UNDER 09-08-03
BEFORE REPLACING 6.0L CYLINDER HEAD GASKETS REFER TO 09-08-03
TO ENSURE OPTIMUM COOLING SYSTEM PREFORMANCE, REFER TO 09-08-05

GENERAL WARRANTY INFORMATION

WARRANTY START DATE 02/03/2005	**BUILD DATE** 01/26/2005	**SALE MILEAGE**	**New Vehicle Base Warranty**

OUTSTANDING FIELD SERVICE ACTIONS

NO CAMPAIGN MESSAGE(S) FOUND

EXTENDED COVERAGES

NO ESP INFORMATION AVAILABLE

WARRANTY REPAIR HISTORY

NO RECENT REPAIR HISTORY ON VEHICLE

Click Here for Full Warranty History

END OF OASIS REPORT FOR **1FMSU45P85EC14606**

Standard Claims List For Model Year 2005

Detailed Vehicle Specification

VIN	VEH LINE	MKT DERIV	BODY CAB	VER SERIES	DRIVE TYPE	PLT CD	TRS CD	ENG CD	PROD DATE	WARR DATE	SELLING DEALER	SELL CNT	TIS
1FMSU45P85EC14606	T/L1	F	T/WD	T/BD	T/E	A1	T/BE	T/YB	26-JAN-2005	03-FEB-2005	152487	USA	1
AWS Claim Key:	449008	**Trx Code:**	1	**Labor Hrs:**	11.7								
Dlr Cd-Sub Cd:	02914 - *	**Name:**	TEXSTAR FORD LINCOLN MERCURY, INC.	**Ph:**	254-9687000	**St:**	TX	**Ctry Cd:**			USA		
Cust Comments:	CHECK DVD PLAYER DONT WORK												
Tech Comments:	CHECK DVD PLAYER INOP, RUN PINPOINT TESTS, FOUND FUSE F2.16 15 AMP BLOWN, GROUND R&R KICK PANEL, OVERHEAD CONSOLES, B PILLAR TRIM PARTIALLY PULI OK, R&R CENTER												
1FMSU45P85EC14606	T/L1	F	T/WD	T/BD	T/E	A1	T/BE	T/YB	26-JAN-2005	03-FEB-2005	152487	USA	13
AWS Claim Key:	3543710	**Trx Code:**	05E16	**Labor Hrs:**	0.7								
Dlr Cd-Sub Cd:	02914 - *	**Name:**	TEXSTAR FORD LINCOLN MERCURY, INC.	**Ph:**	254-9687000	**St:**	TX	**Ctry Cd:**			USA		
Cust Comments:	05E16 RECALL ENGINE MODULE RECALIBRATION												
Tech Comments:	1 RECALIBRATE MODULES PER 05E16 RECALL												
1FMSU45P85EC14606	T/L1	F	T/WD	T/BD	T/E	A1	T/BE	T/YB	26-JAN-2005	03-FEB-2005	152487	USA	13
AWS Claim Key:	3543709	**Trx Code:**	05B32	**Labor Hrs:**	0.2								
Dlr Cd-Sub Cd:	02914 - *	**Name:**	TEXSTAR FORD LINCOLN MERCURY, INC.	**Ph:**	254-9687000	**St:**	TX	**Ctry Cd:**			USA		
Cust Comments:	05B32 RECALL DE GAS BOTTLE LABEL												
Tech Comments:	1 INSTALL LABEL PER 05B32 RECALL												
1FMSU45P85EC14606	T/L1	F	T/WD	T/BD	T/E	A1	T/BE	T/YB	26-JAN-2005	03-FEB-2005	152487	USA	42
AWS Claim Key:	9970399	**Trx Code:**	S07	**Labor Hrs:**	4								
Dlr Cd-Sub Cd:	02914 - *	**Name:**	TEXSTAR FORD LINCOLN MERCURY, INC.	**Ph:**	254-9687000	**St:**	TX	**Ctry Cd:**			USA		
Cust Comments:	CUSTOMER STATES CHECK ENGINE LIGHT ON												
	CHECKED AND VERIFIED CHECK ENGINE LIGHT ON HOOK UP TO IDS CHECKED FOR I												

Tech Comments:	04 07 FOLLOWED FLOW CHART AND INSPECTED TURBO UNISON RING OK NOT COKE CENTER ROTATING HOUSING AND CLEANED VAIN SET REASSEMBLE TURBO AND IN TEST RECHECK SYSTEM OK

1FMSU45P85EC14606	T/L1	F	T/WD	T/BD	T/E	A1	T/BE	T/YB	26-JAN-2005	03-FEB-2005	152487	USA	45

AWS Claim Key:	10428558	**Trx Code:**	E72	**Labor Hrs:**	6.7				
Dlr Cd-Sub Cd:	02914 - *	**Name:**	TEXSTAR FORD LINCOLN MERCURY, INC.	**Ph:**	254-9687000	**St:**	TX	**Ctry Cd:**	USA

Cust Comments:	CUSTOMER STATES THAT ENGINE CRANKS OVER BUT WILL NOT START
Tech Comments:	CHECKED AND VERIFIED NO START HOOK UP TO IDS FOUND FAULT CODE P2291 PER PER TSB 08 18 06 PERFORMED AIR CHECKS FOUND QUICK CONNECT FITTING AT HIGI LEAKING REMOVED HIGH PRESSURE OIL PUMP AND REPLACED FITTING WITH UPDA RECHECK NO